

**Port of Fujairah**

P.O. Box : 787, Fujairah
 United Arab Emirates
 Fax : 09-2228811 (Admin.)
 09-2228555 (Oprts.)
 09-2228312 (Engg.)
 09-2228022 (Marine)

ميناء الفجيرة

ص.ب : ٧٨٧ - الفجيرة
 الإمارات العربية المتحدة
 فاكس : ٩-٢٢٢٨٨١١ (الادارة)
 ٩-٢٢٢٨٥٥٥ (العمليات)
 ٩-٢٢٢٨٣١٢ (الهندسة)
 ٩-٢٢٢٨٠٢٢ (بحرية)

To:	All Agents / Bunkering Companies / De-Sloping Companies / Oil Terminal Users / FTA / Coast Guard / Hydrographic Office-UK		
Attn:	General Manager / Operations Manager		
From:	Capt. Tamer Masoud – Harbour Master		
Facsimile No.:	City: Fujairah	Country:	U.A.E
Ref. No.	MD/FAX/13/0160	Date:	18 April 2019
		No. Pages:	1 +1

Notice To Mariners No. 259

**SUBJECT : UNDERSEA COMMUNICATION CABLE
 NORTH OF LATITUDE 25° 37.0' N**

It has come to our notice that there are many vessels anchored North of latitude 25°37.0' N which displays high risk to the Global Communication Network. The 'undersea communications cable' is essential for the global communication (please find attached sketch of the cable routes) and network operators are repeatedly reporting their concern on the subject.

Also, the anchored vessels at location mentioned above are challenging the safety of vessels passing through the Hormuz.

Mariners are requested to avoid anchoring North of latitude of 25° 37.0' N in order to protect the Global Communication Network.

Affected Charts : Admiralty Chart 2888.

Please advise all your principals and ship masters accordingly.

Thanks & Regards,


 Capt. Tamer Masoud
HARBOUR MASTER

cc : General Manager – PoF
 Dy. Harbour Masters - PoF
 Port Safety Officer - PoF
 Port Security Officer - PoF
 Control Tower.