



Port of Fujairah
P.O. Box : 787, Fujairah
United Arab Emirates
Fax : 09-2228811 (Admin.)
09-2228555 (Oprts.)
09-2228312 (Engg.)
09-2228022 (Marine)

ميناء الفجيرة
ص.ب : ٧٨٧ - الفجيرة
الإمارات العربية المتحدة
فاكس : ٩-٢٢٢٨٨١١ (الإدارة)
٩-٢٢٢٨٥٥٥ (العمليات)
٩-٢٢٢٨٣١٢ (الهندسة)
٩-٢٢٢٨٠٢٢ (بحرية)

To:	All Agents / Bunkering Companies / De-Sloping Companies / Oil Terminal Users / Hydrographic Office UK.		
Attn:	General Manager / Operations Manager		
From:	Capt. Tamer Masoud – Harbour Master		
Facsimile No.:	City: Fujairah	Country:	U.A.E
Ref. No. MD/FAX/16/153	Date: 14 August 2016	No. Pages:	1 + 1

Notice To Mariners No. 212

SUBJECT : INTRODUCTION OF FAIR WAY BUOY & LATERAL RED HAND MARK

Please be advised that a Fair Way buoy and a Lateral Buoy (Red Hand Mark) were installed on 13 August 2016. The coordinates and characteristics of the buoys are given below,

- **Fair Way Buoy**

Coordinate : 25⁰ 08.0' N & 056⁰ 25.0' E
Characteristics : Iso.W.6s

- **Lateral Buoy (Red Hand Mark) (B4)**

Coordinate : 25⁰ 7.5' N & 056⁰ 24.0' E
Characteristics : Fl.R

- **Direction of Traffic Flow**

- Please consider the “Note 1-Port of Fujairah” given in the Admiralty Charts 3723 & 3709 as cancelled (Edition No. 2 dated 04/10/2012).
- Direction of traffic flow is normal as per international maritime convention.
- Vessel calling and leaving South Pilot Station shall keep the Fairway Buoy on their Port Side.

Best Regards,


Capt. Tamer Masoud
HARBOUR MASTER.

C.c : General Manager – PoF
Dr. Salem Khalil – D.I&E
Marketing Manager – PoF
Terminal Manager – PoF
Operations Manager - PoF
Dy. Harbour Master – PoF
Asst. Harbour Master – PoF
Pilots Office
Control Tower.